Welsh Coach House and Stable (University of Pennsylvania, Mask and Wig Club) 310 South Quince Street Philadelphia Philadelphia County Pennsylvania

HATOS

PA

51-PHILA

551A

PHOTOGRAPH

HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Department of the Interior
Washington, D.C. 20240

Form 10-920 (June 1983)

UNITED STATES OF PARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

MAJ MAJ

100

ARCHITECTURAL DATA FORM


	ARCHITECT	URAL DATA FORIV	l	
STATE	CDUNTY		TOWN OR VICINITY	
PENNSYLVANIA	PHILADELPHIA	PHILADELPHIA		
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME)			HABS NO.	
WELSH COACH HOUSE AND STABLE				PA-1518
SECONDARY OR COMMON NAMES OF	STRUCTURE	- <u>-</u>		
University of Pennsylvania, Mask and Wig Club			- · · · · · · · · · · · · · · · · · · ·	
COMPLETE ADDRESS (DESCRIBE LOC	ATION FOR RURAL	SITESI		
	,,,,,,,,,,			
310 South Quince Street	501/0051	A D OULT FOT ION (INC	V 110 E COLUMN	•
DATE OF CONSTRUCTION (INCLUDE	SOURCE)	ARCHITECT(S) (INC	LUDE SOURCE	<i>)</i>
Bet. 1843 and 1853				
SIGNIFICANCE (ARCHITECTURAL AN				
A nice 19th century coach hou Mask and Wig Club, a Universi	ise and stable t	that was later co	onverted int	to a clubhouse for the
l and wig of ab, a onlivers	rcy or remisyiva	anta singing ciu	D.	
STYLE (IF APPROPRIATE)				
MATERIAL DE CONSTRUCTION (INCL	UDE STRUCTURAL	SYSTEMS)	· · · · · · · · · · · · · · · · · · ·	
Stuccoed brick.		Section 5		
SHAPE AND DIMENSIONS OF STRUCT	URE (SKETCHED FL	OOR PLANS ON SEPA	RATE PAGES A	RE ACCEPTABLE)
Approx. 28' (five-bay front)	X 851. See atta	ached floor plans	લ .	
EXTERIOR FEATURES OF NOTE Original exterior features ca though there were a "D" shape on the coach house and a plai	ed window and a in fascia on the	barge cornice in stable.	n the gable	greatly altered, alend, a brick cornice
The following descriptions any ellow pine floor and plaster of folding doors framed and ing stairs in first floor; load LTERATIONS AND ADDITIONS WITH	re the original red walls and co lined with board oft with a trap	interior elemen	ts of the buand second	floors; two large pai
In 1894 the building was conv		lubhouse from pla	ans by archi	itect Wilson Evre. Jr.
See attached floor plan. Further alterations were made in 1901, also from Wilson Eyre, Jr.'s				
plans, and included a new thing	ree-story brick	front addition a	and interior	r work and improve-
PRESENT CONDITION AND USE				
Good; still used as home of t	the Mask and Wig	or Club		
OTHER INFORMATION AS APPROPRIATE				
sources of Information (INCLUE) beter, Richard. Philadelphis Fire Insurance surveys for 33 known.	ia Preserved. Pl	hiladelphia: Tem	ple Univers:	ity Press, 1976.
COMPILER, AFFILIATION				DATE
Susan McCown, Historic Americ	an Buildings Su	ırvey		June 6, 1984

INTERIOR FEATURES OF NOTE (continued from page 1):


with turned posts and wooden floor grates.

See also sketched floor plans on page 3.






FRONT (EAST) ELEVATION -310 South Quince Street-



ALTERED FLOOR PLAN FOR THE USE OF A CLUB, FIRST FLOOR, 1894



DELINEATOR: Susan McCown, Historic American Buildings Survey